



## Гайки шестигранные корончатые



d	m	h	n	d3	e	s
M5	4,0	6,0	1,4	-	8,79	8
M6	5,0	7,5	2,0	-	11,05	10
M8	6,5	9,5	2,5	-	14,38	13
M10	8,0	12,0	2,8	-	17,77	16
M12	10,0	15,0	3,5	16	20,03	18
M14	11,0	16,0	3,5	18	23,35	21
M16	13,0	19,0	4,5	22	26,75	24
M18	15,0	21,0	4,5	25	29,56	27
M20	16,0	22,0	4,5	28	32,95	30
M22	18,0	26,0	5,5	31	35,03	32
M24	19,0	27,0	5,5	34	39,55	36
M27	22,0	30,0	5,5	38	45,20	41
M30	24,0	33,0	7,0	42	50,85	46
M36	29,0	38,0	7,0	50	55,80	55

Материал	
A2 A4	100
A2 A4	100
A2 A4	100
A2 A4	50
A2 A4	50
A2 A4	50
A2 A4	50
A2 A4	25
A2 A4	25
A2 A4	25
A2 A4	25
A2 A4	10
A2 A4	10
A2 A4	10

КРЕПЕЖ