



Гайки-барашки

немецкий тип



d	h	e	m	d2	g min	g max
M4	8,5	18	4,6	8	1,9	2,3
M5	11,0	24	6,5	11	2,3	2,8
M6	15,0	30	8,0	13	2,3	3,3
M8	18,0	36	10,0	16	2,8	4,4
M10	23,0	48	12,0	20	4,4	5,4
M12	31,0	62	14,0	23	4,9	6,4
M14	35,0	70	17,0	29	6,4	7,5
M16	35,0	70	17,0	29	6,4	7,5

Материал	
A2 A4	50
A2 A4	50
A2 A4	50
A2 A4	50
A2 A4	50
A2 A4	25
A2 A4	10
A2 A4	10

КРЕПЕЖ