


DIN 562

Гайки квадратные низкие

без фаски



d	m	e	s
M1,6	1,0	4,0	3,2
M2	1,2	5,0	4,0
M2,5	1,6	6,3	5,0
M3	1,8	7,0	5,5
M4	2,2	8,9	7,0
M5	2,7	10,2	8,0
M6	3,2	12,7	10,0
M8	4,0	16,5	13,0
M10	5,0	21,5	17,0

Материал	
A2 A4	500
A2 A4	500
A2 A4	500
A2 A4	500
A2 A4	500
A2 A4	200
A2 A4	200
A2 A4	200
A2 A4	100