


Приварная резьбовая шпилька (болт приварной) для контактной сварки конденсаторным разрядом СД.



M10							X		X		X		X		
-----	--	--	--	--	--	--	---	--	---	--	---	--	---	--	--

Нержавеющая сталь

d1	l1														
	6	8	10	12	15	16	20	25	30	35	40	45	50	55	60
M3	X	X	X	X	X	X	X	X	X						
M4	X	X	X	X	X	X	X	X	X	X	X				
M5	X	X	X	X	X	X	X	X	X	X	X	X			
M6		X	X	X	X	X	X	X	X	X	X	X	X	X	
M8			X	X	X	X	X	X	X	X	X	X	X	X	X
M10							X		X		X				

Латунь

d1	11														
	6	8	10	12	15	16	20	25	30	35	40	45	50	55	60
М3	X	X	X	X	X	X	X	X	X						
М4	X	X	X	X	X	X	X	X	X	X	X				
М5		X	X	X	X	X	X	X	X	X					
М6		X	X	X	X	X	X	X	X	X	X				
М8			X	X	X	X	X	X	X	X	X				

Алюминий

d1	11														
	6	8	10	12	15	16	20	25	30	35	40	45	50	55	60
М3	X	X	X	X	X	X	X	X	X						
М4	X	X	X	X	X	X	X	X	X	X	X				
М5		X	X	X	X	X	X	X	X	X	X	X			
М6		X	X	X	X	X	X	X	X	X	X	X	X		
М8			X	X	X	X	X	X	X	X	X				