


Шайбы полиамидные плоские без фаски

тип А



d	для резьбы	d2	h
2,2	M2	5	0,3
2,7	M2,5	6	0,5
3,2	M3	7	0,5
4,3	M4	9	0,8
5,3	M5	10	1,0
6,4	M6	12	1,6
8,4	M8	16	1,6
10,5	M10	20	2,0
13	M12	24	2,5
15	M14	28	2,5
17	M16	30	3,0
19	M18	34	3,0
21	M20	37	3,0
25	M24	44	4,0
28	M27	50	4,0
31	M30	56	4,0

Материал	
Polyamid	1000
Polyamid	1000
Polyamid	1000
Polyamid	1000
Polyamid	1000
Polyamid	1000
Polyamid	1000
Polyamid	500
Polyamid	500
Polyamid	500
Polyamid	200
Polyamid	200
Polyamid	200
Polyamid	100
Polyamid	50
Polyamid	25