


Гайки квадратные

с фаской



d	dw min	m	e max	s
M5	6,7	4,0	11,3	8
M6	8,7	5,0	14,1	10
M8	11,5	6,5	18,4	13
M10	14,5	8,0	22,6	17
M12	16,5	10,0	25,4	19
M16	22,0	13,0	33,9	24

Материал	
A2-70 A4-80	200
A2-70 A4-80	200
A2-70 A4-80	200
A2-70 A4-80	100
A2-70 A4-80	100
A2-70 A4-80	100

КРЕПЕЖ