



Гайки шестигранные колпачковые высокие



d	P	h	m	dk	e	s
M3	0,50	7	2,4	5,5	6,01	5,5
M4	0,70	8	3,2	6,5	7,50	7
M5	0,80	10	4,0	7,5	8,63	8
M6	1,00	12	5,0	9,5	10,89	10
M7	1,00	12	5,0	9,5	10,89	13
M8	1,25	15	6,5	12,5	14,20	13
M10	1,50	18	8,0	16,0	17,59	17
M12	1,75	22	10,0	18,0	19,85	19
M14	2,00	25	11,0	21,0	22,78	22
M16	2,00	28	13,0	23,0	26,17	24
M18	2,50	32	15,0	26,0	29,56	27
M20	2,50	34	16,0	28,0	32,95	30
M22	2,50	39	18,0	33,0	35,03	34
M24	3,00	42	19,0	34,0	39,55	36
M27	3,00	47	20,0	40,0	47,30	41
M30	3,50	52	24,0	42,0	52,00	46

Материал	
A2 A4	500
A2 A4	500
A2 A4	500
A2 A4	500
A2 A4	200
A2 A4	200
A2 A4	100
A2 A4	100
A2 A4	50
A2 A4	50
A2 A4	25
A2 A4	25
A2 A4	10
A2 A4	10
A2 A4	10
A2 A4	10