



Шайбы упорные быстросъёмные

для валов



d	Для Ø	d3	s	a
1,2	1,4 - 2,0	3,25	0,30	1,01
1,5	2,0 - 2,5	4,25	0,40	1,28
1,9	2,5 - 3,0	4,80	0,50	1,61
2,3	3,0 - 4,0	6,30	0,60	1,94
3,2	4,0 - 5,0	7,30	0,60	2,70
4	5,0 - 7,0	9,30	0,70	3,34
5	6,0 - 8,0	11,30	0,70	4,11
6	7,0 - 9,0	12,30	0,70	5,26
7	8,0 - 11,0	14,30	0,90	5,84
8	9,0 - 12,0	16,30	1,00	6,52
9	10,0 - 14,0	18,80	1,10	7,63
10	11,0 - 15,0	20,40	1,20	8,32
12	13,0 - 18,0	23,40	1,30	10,45
15	16,0 - 24,0	29,40	1,50	12,61
19	20,0 - 31,0	37,60	1,75	15,92
24	25,0 - 38,0	44,60	2,00	21,88

Материал	
1.4122	1000
1.4122	1000
1.4122	1000
1.4122	1000
1.4122	1000
1.4122	1000
1.4122	1000
1.4122	1000
1.4122	500
1.4122	500
1.4122	500
1.4122	500
1.4122	200
1.4122	200
1.4122	100
1.4122	50