

Насадки
TORX C-form

Размер	Длина, мм	Штук в упаковке	Код	Хвостовик
T8	25	3	B-23581	C-form
T10	25		B-23597	
T15	25		B-23606	
T20	25		B-23612	
T25	25		B-23628	
T27	25		B-23634	
T30	25		B-23640	
T40	25		B-23656	
T20, 25, 30	25	10	B-24533	
T15	25		P-06339	
T20	25		P-06345	
T25	25		P-06351	
T27	25		P-06367	

Насадки
TORX E-form (MZ)

Размер	Длина, мм	Штук в упаковке	Код	Хвостовик
T8	50	3	B-25351	E-form (MZ)
T9	50		B-25367	
T10	50		B-25373	
T15	50		B-25389	
T20	50		B-25395	
T25	50		B-25404	
T27	50		B-25410	
T30	50		B-25426	
T40	50		B-25432	
T20, 25, 30	50		B-26191	

Насадки
HEX C-form

Размер	Длина, мм	Штук в упаковке	Код	Хвостовик
1,5	25	3	B-23662	C-form
2	25		B-23678	
2,5	25		B-23684	
3	25		B-23690	
4	25		B-23709	
5	25		B-23715	
6	25		B-23721	
8	25		B-23737	
3	50	10	B-25448	
4	50		B-25454	
5	50		B-25460	
6	50		B-25476	
2,5	25		P-21369	
3	25		P-21375	
5	25		P-21397	
6	25		P-21406	
8	25		P-21412	

Насадки HEX E-form (MZ)



Размер	Длина, мм	Штук в упаковке	Код	Хвостовик
M4	110	1	1R228	E-form (MZ)
M5	110		1R229	
M6	110		1R230	
M8	110		1R231	
M5	160	1	1R015	E-form (MZ)
M6	140		1R016	
M8	200		1R017	

Насадки с плоским шлицем
(SLOTTED) E-form (MZ)

Размер	Длина, мм	Штук в упаковке	Код	Хвостовик
SL1,6x8,0	25	10	P-06242	E-form (MZ)
SL0,5x3	50		B-25270	
SL0,5x4	50	3	B-25286	
SL0,6x4,5	50		B-25292	
SL0,8x5,5	50		B-25301	
SL1,0x5,5	50		B-25317	
SL1,2x6,5	50		B-25323	
SL1,2x8,0	50		B-25339	
SL1,6x8,0	50		B-25345	